
Evaluation of Household Water Quality in Culpeper County, Virginia NOVEMBER - DECEMBER 2008 VIRGINIA HOUSEHOLD WATER QUALITY PROGRAM

Background

More than 1.5 million Virginia households use private water supplies such as wells, springs and cisterns. The Virginia Household Water Quality Program (VAHWQP) began in 1989 with the purpose of improving the water quality of Virginians reliant on private water supplies. Since then the program has conducted drinking water clinics in 86 counties across Virginia and has analyzed samples from more than 12,500 households. In 2007, the Virginia Master Well Owner Network (VAMWON) was formed to support the VAHWQP. Virginia Cooperative Extension (VCE) agents and volunteers participate in a 1-2 day VAMWON training workshop that covers private water system maintenance and protection, routine water testing, and water treatment basics. They are then able to educate others about private water supplies. More information about these programs may be found at our website: www.wellwater.bse.vt.edu.

Private water sources, such as wells and springs, are not regulated by the U.S. Environmental Protection Agency (EPA). Although private well construction regulations exist in Virginia, private water supply owners are responsible for the maintenance of their water systems, for monitoring water quality and for taking appropriate steps to address problems should they arise. The EPA public drinking water standards are good guidelines for assessing water quality. *Primary drinking water standards* apply to contaminants that can adversely affect health and are legally enforceable for public water systems. *Secondary drinking water standards* are non-regulatory guidelines for contaminants that may cause nuisance problems such as bad taste, foul odor, or staining. Testing water annually, and routinely inspecting and maintaining a water supply system will help keep water safe.

Geology

Culpeper County is located in the Piedmont physiographic province of Virginia, which extends from the Blue Ridge Mountains to the Fall Line,

which essentially parallels I-95. Hard, crystalline, igneous and metamorphic geologic formations dominate this region, interspersed with some areas of sedimentary rocks. Most significant water supplies are found within a few hundred feet of the surface due to the size and number of faults and fractures that store and transmit ground water. Due to the diverse subsurface geology in this region, there are wide variations in ground water quality and well yields. A few areas, for example, have problems with high iron concentrations and acidic water. Because of the range in ground water quality and quantity in this region, as well as the varying potential for contamination, well site evaluation and routine water quality monitoring are critical (GWSPSC, 2008).

Overview

In December 2008, 41 residents of Culpeper County participated in a drinking water clinic sponsored by the local Virginia Cooperative Extension (VCE) office and the Virginia Household Water Quality Program. Clinic participants attended educational meetings where they learned how to collect a water sample, and after receiving a confidential water sample analysis, how to interpret their water test results and address potential issues. The most common household water quality issues identified were low pH, nitrate, manganese and the presence of total coliform bacteria. Figure 1, found at the end of this report, shows these common water quality issues along with basic information on standards, causes, and treatment options.

Drinking Water Clinic Process

Any Culpeper resident relying on a well, spring or cistern was welcome to participate in the clinic. Advertising began 8 weeks prior to the first meeting and utilized local media outlets, announcements at other VCE meetings, and word of mouth. Pre-registration was encouraged.

Kickoff meeting: Participants were given a brief presentation that addressed common water quality issues in the area, an introduction to parameters included in the analysis, and instructions for

collecting their sample. Sample kits with sampling instructions and a short questionnaire were distributed. The questionnaire was designed to collect information about characteristics of the water supply (e.g. age, depth, location), information about the home (e.g. age, plumbing materials, existing water treatment) and any existing perceived water quality issues. The purpose of the clinic is to build awareness among private water supply users about protection, maintenance and routine testing of their water supply.

Participants were instructed to drop their samples and completed questionnaires off at a predetermined location on a specific date and time.

Sample collection: Following collection at a central location in Culpeper, all samples were iced in coolers and promptly transported to Virginia Tech for analysis.

Analysis: Samples were analyzed for the following water quality parameters: iron, manganese, nitrate, chloride, fluoride, sulfate, pH, total dissolved solids (TDS), hardness, sodium, copper, total coliform bacteria, and *E. coli*. General water chemistry and bacteriological analyses were performed by the Department of Biological Systems Engineering Water Quality Laboratory at Virginia Tech. The Virginia Tech Soils Testing Laboratory performed the elemental constituent analyses. All water quality analyses were performed using standard analytical procedures.

The EPA Safe Drinking Water Standards, which are enforced for public water systems in the U.S., were used as guidelines for this program. Water quality parameters out of range of these guidelines were identified on each test report. Test reports were prepared and sealed in envelopes for confidential distribution to clinic participants.

Interpretation meeting: At this meeting, participants received their confidential water test reports and VCE personnel made a presentation providing a general explanation of what the numbers on the reports indicated. In addition, general tips for maintenance and care of private water supply systems, routine water quality testing recommendations and possible options for correcting water problems were discussed. Participants were encouraged to ask questions and discuss findings either with the rest of the group or one-on-one with VCE personnel after the meeting.

Findings and Results

Profile of Household Water Supplies

The questionnaire responses, provided by all 41 participants at the clinic, helped to characterize the tested water supplies. All participants in the Culpeper clinic indicated their water supply was a well.

Participants were asked to classify their household environment as one of the following four categories: (1) a farm (2) a remote, rural lot (3) a rural community (4) a housing subdivision.

For the Culpeper clinic, rural community was the most common answer at 44%, followed by rural lot at 20%, farm at 17%, and subdivision at 17%.

Sources of potential contamination near the home (within 100 feet of the well) were identified as septic system drain fields (22%) followed by home-heating oil tanks (20%). Larger, more significant potential pollutant sources were also proximate (within one-half mile) to water supplies, according to participants. Nearly half indicated that their water supply was located within one-half mile of a major farm animal operation and 15% indicated that their supply was within one half-mile of a field crop production operation.

The type of material used for water distribution in each home was also described by participants on the questionnaire. The two most common pipe materials were copper (46%) and plastic (43%).

To properly evaluate the quality of water supplies in relation to the sampling point, participants were asked if their water systems had water treatment devices currently installed, and if so, the type of device(s). Forty-four percent of participants reported at least one treatment device installed. The most commonly reported treatment device was a sediment filter (39%). Other reported devices included iron filter (7%), and water softener, acid neutralizer, and carbon filter (5% each).

Participants' Perceptions of Household Water Quality

Participants were asked whether or not they perceived their water supply to have any of the following characteristics: (1) corrosive to pipes or plumbing fixtures; (2) unpleasant taste; (3) objectionable odor; (4) unnatural color or appearance; (5) floating, suspended, or settled particles in the water; and (6) staining of plumbing fixtures, cooking appliances/utensils, or laundry.

Staining problems were reported by 73% of clinic participants. "Rusty" stains were reportedly experienced by 32% of participants followed by "blue/green" stains at 29%. Seventeen percent of participants reported black or grey stains.

Twenty-six percent of participants at the clinic responded that floating, suspended, or settled particles were found in their water, the most common of which were "white flakes" (12%).

Twenty-four percent of participants reported that their water had an unnatural color or appearance. Of those 24%, 9% identified the issue as an "Oily film" while 7% reported a "yellow color."

An objectionable odor was reported by 19% of participants, of which the most common was described as smelling like "rotten eggs" (15%).

Fourteen percent of clinic participants responded that their water had an unpleasant taste. "Metallic" taste was the most commonly reported taste (8%) followed by "bitter" (5%).

Bacteriological Analysis

Private water supply systems can become contaminated with potentially harmful bacteria and other microorganisms. Microbiological contamination of drinking water can cause short-term gastrointestinal disorders, such as cramps and diarrhea that may be mild to very severe. Other diseases that may be contracted from drinking contaminated water include viral hepatitis A, salmonella infections, dysentery, typhoid fever, and cholera.

Microbiological contamination of a water supply is typically detected with a test for total coliform bacteria. Coliform bacteria are present in the digestive systems of humans and animals and can also be found in the soil and decaying vegetation. While coliform bacteria do not cause disease, they are indicators of the possible presence of disease causing bacteria, so their presence in drinking water warrants additional testing.

Since total coliform bacteria are found throughout the environment, water samples can become accidentally contaminated during sample collection. Positive total coliform bacteria tests are often confirmed with a re-test. If coliform bacteria are present in a water supply, there are several possible pathways or sources, including: (1) improper well location or inadequate construction or maintenance (well too close to septic, well not fitted with sanitary cap), (2) contamination of the household plumbing system (e.g. contaminated faucet, water heater), and (3) contamination of the groundwater itself

(perhaps due to surface water/groundwater interaction).

The presence of total coliform bacteria in a water sample triggers testing for the presence of *E. coli* bacteria. If *E. coli* are present, it indicates that human or animal waste is entering the water supply.

Of the 41 samples collected, 39% tested positive (present) for total coliform bacteria. Subsequent *E. coli* analyses for all of these samples were negative (absent).

Program participants whose water tested positive (present) for total coliform bacteria were encouraged to retest their water to rule out possible cross contamination, and were given information regarding emergency disinfection, well improvements, and septic system maintenance. After taking initial corrective measures, participants were advised to have their water retested for total coliform, followed by testing for *E. coli*, if warranted. In addition, participants were provided with resources that discussed continuous disinfection treatment options.

Table 1, found at the end of this report, shows the general water chemistry and bacteriological analysis contaminant levels for the Culpeper County drinking water clinic participants.

Chemical Analysis

As mentioned previously, all samples were tested for the following parameters: iron, manganese, nitrate, chloride, fluoride, sulfate, pH, total dissolved solids (TDS), hardness, sodium, and copper. Selected parameters of particular interest for the Culpeper drinking water clinic samples are discussed below.

pH

pH is a measure of the acidity or alkalinity of a substance. The EPA suggests the pH for public drinking water be between 6.5 and 8.5. Of the 41 Culpeper clinic samples, 60% were below the lower recommended pH of 6.5, indicating acidic water. Although not a health concern in itself, acidic water may be corrosive and can potentially leach metals like copper and lead from plumbing components. An option for dealing with low pH water is to install an acid neutralizing filter which raises pH by passing the water through a medium of calcite and/or magnesium oxide. If the age of a home or the plumbing materials present in a home pointed to potential health problems associated with metals leaching into water, participants were encouraged to pursue lead testing, which is not currently available through the VAHWQP.

Nitrate

High levels of nitrate may cause methemoglobinemia or “blue-baby” disease in infants under six months of age. The EPA public water supply standard is 10 milligrams per liter (mg/L) nitrate-nitrogen. Levels approaching 3-5 mg/L or higher may indicate contamination of the water supply by fertilizers or organic waste, so use of this water for infants under 6 months of age is discouraged.

Nitrate is tasteless, odorless, and easily dissolved, meaning it moves freely with water. Of the 41 Culpeper clinic samples, 38% exceeded the 10 mg/L standard. Participants were warned that boiling water increases concentration of any dissolved pollutant like nitrates and thus is not a variable treatment option. Possible nitrate treatment options include distillation, reverse osmosis, ion exchange or use of another water source for infants.

Iron

Iron in water is considered a nuisance and does not usually present a health risk. The EPA recommended maximum contaminant level is for iron 0.3 mg/L. Excessive iron can cause brown-orange stains on plumbing fixtures and laundry. At high enough levels, iron in water may produce a bitter, metallic taste.

Three percent of the Culpeper clinic samples had iron concentrations exceeding 0.3 mg/L. Depending on if the iron is in solution (dissolved) or particulate form, treatment options for excessive iron includes a water softener, aeration and filtration, ozonation, and distillation.

Manganese

Like iron, manganese is a nuisance contaminant and does not present a health risk. The EPA recommended maximum contaminant level is 0.05 mg/L. Excessive manganese concentrations may give water a bitter taste and can produce black stains on laundry, cooking utensils, and plumbing fixtures.

Twelve percent of Culpeper clinic samples tested above 0.05 mg/L. Treatment options for manganese include a water softener, reverse osmosis or distillation.

Hardness

Hard water contains high levels of calcium and magnesium ions that dissolve into groundwater while it is in contact with limestone and other

minerals. Hard water is a nuisance and not a health risk.

About three percent of the Culpeper clinic samples were considered to be “very hard” (exceeding 180mg/L of hardness). Hard water is indicated by scale build-up in pipes and on appliances, decreased cleaning action of soaps and detergents, and reduced efficiency and lifespan of water heaters. Ion exchange water softeners are typically used to remove water hardness.

Copper

The EPA health standard for copper in public drinking water supplies is 1.3 mg/L. If the concentration of copper exceeds this, it can cause gastrointestinal illness. Children and infants may be particularly susceptible. Indications of copper include bitter or metallic tasting water and blue-green stains on plumbing fixtures.

Of the 41 Culpeper clinic samples, 3% exceeded the EPA standard. The maximum concentration measured was 2 mg/L. Raising the pH of the water using an acid neutralizing filter will make the water less corrosive and may reduce copper levels.

Conclusions

Participants were asked to complete a program evaluation survey following the interpretation meeting. Of those who completed the survey, 71% indicated they would test their water either annually or at least every few years. Most indicated they would discuss what they learned during their participation in the clinic with others. Finally, nearly half (43%) of participants indicated that based on their analysis results, they would perform additional testing. Another 43% of participants stated that they would try to determine the source of pollution affecting their water supply. Eighteen percent said they would pump out their septic system and an additional 18% reported they would grade the area around their well or improve maintenance of their water system.

References

Mayo Clinic. Sodium: How to tame your salt habit now.
<http://www.mayoclinic.com/health/sodium/NU00284>.
Accessed online 9/2010.

U.S. Environmental Protection Agency. Drinking Water Contaminants.
<http://www.epa.gov/safewater/contaminants/index.html>. Accessed online 9/2008.

Virginia Department of Environmental Protection Groundwater Protection Steering Committee. Virginia's Five Physiographic Provinces.
<http://www.deq.state.va.us/gwpsc/geol.html>. Accessed online 9/2008.

Additional Resources

For more information about the water quality problems described in this document, please refer to our website. Here you will find resources regarding household water testing, interpretation, and solutions to water quality problems.
www.wellwater.bse.vt.edu/resources.php

Acknowledgements

Many thanks to the residents of Culpeper county who participated in the evaluation of their household water quality.

The Water Quality Laboratory of the Department of Biological Systems Engineering (Gail Zatcoff) and Soils Testing Laboratory of the Department of Crop and Soil Environmental Sciences (Athena Tilley) at Virginia Tech were responsible for water quality analyses, as well as data management.

Special thanks to Craig Jebson of Country Water Systems in Culpeper for a generous donation made to support this program.

This document was prepared by Brian L. Benham, Associate Professor and Extension Specialist at Virginia Tech; Erin James Ling, Extension Water Quality Program Coordinator; Carl Stafford, Agriculture and Natural Resources Agent, Culpeper County; Jen Pollard, Extension Staff; Caty Gordon, undergraduate student intern; and Scott Forrester, graduate student intern.

Common Water Quality Issues in 2008 Culpeper Drinking Water Clinic (41 participants)




Figure 1. The most common household water-quality issues found in the 41 Culpeper clinic participant samples were high levels of manganese and nitrate, low pH, and the presence of total coliform bacteria.

**2008 Culpeper County
VAHWQP Drinking Water Clinic Results
N = 41 participants**

Test	Standard	Average	Maximum Value	% Exceeding guideline based on EPA drinking water standards
Iron (mg/L)	0.3	0.08	2	2.5
Manganese (mg/L)	0.05	0.02	0.19	12.5
Hardness (mg/L)	180	63.6	240.8	2.5
Sulfate (mg/L)	250	4.7	24.8	0
Chloride (mg/L)	250	8	44	0
Fluoride (mg/L)	2	0.1	0.9	0
Total Dissolved Solids	500	106	357	0
pH	6.5 to 8.5	6.4	7.8	60.0 (below 6.5)
Copper (mg/L)	1	0.2	2	2.5
Sodium (mg/L)	20	5.7	13.4	0
Nitrate - N (mg/L)	10	10	78.8	37.5
Total Coliform Bacteria	ABSENT	-	-	39 (PRESENT)
E. coli Bacteria	ABSENT	-	-	0 (PRESENT)

Table 1. General water chemistry and bacteriological analysis contaminant levels for Culpeper county drinking water clinic participants (N=41). This program uses the EPA *primary* and *secondary standards* of the Safe Drinking Water Act. While these standards are enforced by law for public water systems, this program uses them only as guidelines for the private water systems tested.